NATIONA, PARK SERVICE Washington D.C. 20240

B- 4081 MAGI# 0440812404

HISTORIC PRESERVATION CERTIFICATION APPLICATION—PART 1

Instructions: Applicant should read the instructions carefully before completing application. No certification may be made by assistant and application form has been received. Use typewriter or print clearly in dark ink to complete the application form: If additional space is not a find complete Part 1, use the reverse side or a separate plain sheet of paper clearly indicating the owner's name and mailing address. Fan 1 of this application may be completed and sent to the appropriate State Historic Preservation Officer at anytime during the year.

APR 1 0 3984

		*		VLU TO 1204
	TION OF SIGNIFICAN			
1. Name of property:N	/A		MAF	RYLAND HISTORICA
Address of property:	/A 7 S. Fremont Avenue			TRUST
				27.70
Name of historic district li	n which property is located: Ri	dgely's Delight	State 2007	Zip C. de< 16.50_
D decertification (structur	or: contributes to significance of th re does not contribute to signific (for donation of easement on st	cance of the district)	rvation purpose s).	
 Description of Physical Ap (see instructions for map 	ppearanc e: and photograph requirements-u	se reverse side il necessa	icy)	
See reverse.				
 Statement of Significance (use reverse side if neces. 				
See reverse.			15	
	of Owner: gel and Ralph Manus Beverly Drive Suite	502		
	receiped by			
CityBeverly Hi	lls ·		State CA	Zip Code _90212
Telephone number (durin	g day); Area Code			
I hereby aftest that the inform	ation I have provided is to the be	st of my knowledge, correc	ct, and that I am owner of	the property described above
Signature	W/ 5-11-12	(A	GELT)	Date
Social Security Number or Tax;	payer Identification Number P.	Sigel Waster	R. Manus	
For office use only				K BERT SERVICE STORY OF STORY 4
The structure described above is the character of the district.	s included within the boundaries o	of a Registered Historic Dis	trict and E contributes	☐ does not contributate
The structure O appears O o nominated to the National Regi	foes not appear to meet National ster in accord with the Departm	Register Criteria for Evalua ent of the Interior procedu	Mich (36 CFR 50.6) and (ures (36 GRF 50).	will likely Combine the
will fixely 12 will not be no	rict which I appears I does ominated to the National Regi appear to contribute to the ch setting National Register criteria.	ster in accord with Depa aracter of said district or	artment of the Interior	procedures (35 CFR (-))
Signature			the land of the la	Date
Committee Co	Profusion Officer			

PART I #2

617 S. Fremont Avenue is a 3 story, brick end row unit. The original use was resitial on the 2nd and 3rd stories and commercial on the first. The circa 1850 building has front facade that faces west. It also has a store-front on the first floor.

The roof, which appears to have been flat with a tar and paper covering has been almost completely destroyed through fire damage. The entire 2 story rear section of the building is missing.

The front facade has a metal cornice at roof level. The cornice over the first substore-front is made of wood and has deteriorated. Windows on the 2nd and 3rd stories are slightly arched with a brick arch over the opening. Window sashes are missing but the sills are intact. The brink in the front facade has been painted but the paint has such away.

The entrance to the building is on the diagonal facing south-west. Both the foor a transom are missing. The store front windows, which are on the west and south walls adjacent to the door, are also missing.

In the rear of the building, there is one window in the loft area, one door on the second level, and one door on the first level. Windows on the 1st and 2nd level have been cemented in. The rear of the building shows evidence that there was an addition there.

Because of the fire damage and collapsing roof, we were unable to take second and third floor photographs. From the rear door, however, we could see that the party wall between 617 and 615 had been removed on the first floor.

An engineering report documenting this condition will be forthcoming.

PART I #3

The significance of 617 S. Fremont Avenue as a historic residence lies in the fact that it is an integral part of the Ridgely's Delight historic district. Ridgely's Delight has been certified as eligible for listing in the Federal Ristoric Register and has already been certified as a municipal historic district.

Originally, the area of Ridgely's Delight sprang up around a Susquehamoch Indian trail. Early settlers stamped a path through the area that connected it to the colonies to the north and south.

In 1714, a survey was undertaken for a Mr. John Parrish on a tract of land named Brotherly Love. Col. Charles Ridgely resurveyed Brotherly Love in 1732 and combined it with several other tracts of land. One of the tracts was Howard's Timber Neck, which Ridgely's wife, Rachel, had received as an inheritance from he grandfather, the original patentee (1668). Fremont Avenue was a part of Howard's Timber Neck which was combined with other tracts to form Ridgely's Delight.

617 S. Fremont Avenue is very typical of the federal and Italianate style houses that characterize the neighborhood. Important architectural features of the house are its diminishing window size and the loft area. These features can be found on many of the homes in the Ridgely's district.

This house sits near the western border of the Ridgely district. From Martin Luther King, Jr. Boulevard, the house is very visible. As this is a vi'm used thoroughfare, by both Faltimoreans and "out-of-towners", the location and condition of this house is important to the entire district.

B-4081 617 S. Fremont Ave Block 861 Lot 030 Baltimore City Baltimore West Quad.

